



Photo 1. View of good revegetation in the southern (on right) and eastern (in background) portions of the project area.





Photo 2. View of dried knapweed plants within the northern portion of the project area.



Photo 3. View of vegetated silt trap and vegetated swale functioning properly as a stormwater diversion.