



Photo 1. View of rill erosion in slope in western portion of project area.





Photo 2. View of stormwater erosion and downcutting in roadside ditch along graveled portion of access road.





Photo 3. View of stormwater erosion on road surface of un-graveled portion of access road within project area upslope from project facilities.



Photo 4. Another view of stormwater erosion and exposed rocks on surface of un-graveled access road near project facilities.