



Photo 1. View from southeastern corner of project area facing center. Large area in foreground does not appear necessary for project activities and needs interim reclamation.



Photo 2. View of eastern edge of project area from southeastern corner facing northward.





Photo 3. View of southern edge of project area from southeastern corner facing westward.



Photo 4. View of stormwater diversion along northern edge of project area.





Photo 5. View of Russian thistle debris around project facilities. Unused portions of this area need revegetation and Russian thistle debris needs to be removed and disposed of properly.