



Photo 1. View of eastern portion of project area that appears to have recently undergone reclamation activities.



Photo 2. View of area in western portion of project area that does not appear necessary for production operations.



Photo 3. View of erosion in southwestern corner of project area.



Photo 4. View of armored culvert in southwestern corner of project area.



Photo 5. View of silt trap needing to be cleaned out in southwestern corner of project area.



Photo 6. View of erosion along western edge of project area.