

**Dugan Production Co Operator #25250
Tiffany #1 API# 05-067-06498
Inspection #674601260**

Existing Well Sign and Emergency
Contact Number



Spill/ saturated soils from unbermed
fiberglass open top tank; moving SW
toward production equipment.



Spill/ saturated soils from unbermed
open to tank; Moving NE and away
from equipment.



Damaged/ breached wildlife screen over fiberglass open top tank. No existing tank sign in place.



Chemical containment full of fluid, minimal freeboard, and without wildlife screen/ protection.



Chemical containment with fluid/ stained soils around equipment.



Steel open top tank (Near Dehydrator) with no sign; Integrity in question; Fluid in containment area; torn poly liner; unmaintained earthen berm.



Damaged wildlife screen on steel open top tank; Trash in containment area.



Free lube oils observed on compressor skid; Stained gravel/ soils on ground adjacent to equipment.



Inadequate storage of fuel containers;
No spill prevention/ covering in place;
Stained soils under equipment.



Undesirable vegetation under and
around heated/ fired equipment.



Heavily damaged/ non operable gate
on access road leading to well pad.



Unmarked Rig Anchor.

