



Photo 1. View from northwestern corner of project area facing center. Vegetation is progressing within the interim reclamation area.



Photo 2. View of southern edge of project area from southwestern corner facing eastward.





Photo 3. View of eastern edge of project area from southeastern corner facing northward.



Photo 4. View of tunnel erosion forming within eastern portion of well pad.





Photo 5. View of rill erosion in northeastern corner of well pad.