



Photo 1. View of revegetation along the fill slope on the southern edge of the project area from the southwestern corner facing eastward.



Photo 2. View of large slash pile along western edge of the project area.





Photo 3. View of northern portion of project area from northeastern corner facing westward.



Photo 4. View from northeastern corner of project area toward center.





Photo 5. View of rill erosion along eastern edge of the project area from well pad entrance facing northward.