



Photo 1. View from well pad entrance to center. One well on location.





Photo 2. View of vegetated stormwater diversion ditch adjacent to northern edge of working area.





Photo 3. View of thistle rosette in northern portion of project area.





Photo 4. View of vegetation that appears to be stressed by grazing pressure within northern portion of interim reclamation area.





Photo 5. View of cobble revetment along stormwater channel exiting the southeastern corner of the project area.





Photo 6. View of rill erosion and unvegetated slope in western portion of project area.