



Photo 1. View of stockpiled materials in eastern portion of project area.





Photo 2. View of unused equipment in eastern portion of project area.



Photo 3. View of debris and unused equipment in northern portion of project area.





Photo 4. View from southwestern corner of project are facing center. Large tarps, woody debris, and trash are spread across the interim reclamation area.





Photo 5. View of Scotch thistle (*Onopordum acanthium*) plants within the interim reclamation area.



Photo 6. View of tall weeds around project facilities.





Photo 7. View of stormwater erosion in northeastern corner of project area from unstabilized cut-slope onto well pad.