



Photo 1. View of dried weeds near the project facilities that need to be removed and controlled.





Photo 2. View of Russian thistle plants in the working area that need to be removed.





Photo 3. View of western portion of the project area from northwestern corner facing southward.



Photo 4. View from southeastern corner of project area facing center. Good revegetation here.





Photo 5. View of vegetated stormwater diversion swale that is sinuous and appears to be functioning properly.





Photo 6. View of rill erosion in cut-slopes along access road near well pad entrance facing northward.