

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 1: Gate and cattle guard at the beginning of the access road.



photo 2: Access road goes across the creek and goes north to the location.

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 7: Metal ring (culvert) remains in the center of the location.



photo 8: Most of the location is completely bare of vegetation.

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 6: Facing west from the access road on the east side of location.



photo 6: Facing south towards the pad from the northeast corner of the location.

Site Photos: API# 05-055-06306

Date: December 4, 2014



photo 6: Erosion is occurring off the slope and down the access road.



photo 6: Culvert remains in creek crossing.