

Hagan Federal 22-8A

Inspection# 675200924

Reclaimed cut slope with hydro-mulch.



Frac tank to be removed to comply with COGCC rules.



Dirt/gravel pile to be removed or
have stormwater BMPs in place
around base.

