



Photo 1. View of numerous Musk thistle rosettes established in the project area.



Photo 2. View of deep rills (more than 1 foot deep) and sediment runoff in western portion of project area.



Photo 3. View of rill erosion and sediment deposition in southern portion of project area.



Photo 4. View of sediment run-on and erosion onto well pad in northern portion of project area.



Photo 5. View of large amounts of sediment in stormwater diversion channel in northern portion of project area. Culvert in background is filling with sediment.



Photo 6. View of stormwater erosion outside of project area from concentrated flows not properly de-energized exiting the culvert at the well pad entrance.