

**BP America Production Company
Floirine Hudspeth A2 API 05-067-08937
COGCC Field Inspection # 674601294 12/11/14**

Subdivision sign and well pad in background.



Produced water tank without signage to meet rule 210d requirements.



Unpainted produced water tank lid.



Disconnected/ unused chemical injection system.



View of wellhead/ equipment looking northwest.



Upslope stormwater ditch/ berm running along west side of well pad.



Breached/ eroded area of storm water ditch/ berm at the tie in to the drain system. Stormwater run on and accumulation on well pad.



Stormwater accumulation on location from breached ditch and low lying area adjacent to south fence line.



Stormwater accumulation/ ponding on well pad. View looking west toward ditch.



Location perimeter fencing damage along area of stormwater ponding.



East side location, recently mowed. Large well pad footprint inside fenced area.



Low lying area/ earthen trough running north- south across well pad behind wellhead and equipment used to catch/ divert stormwater.



Low lying area outside south fence line accumulating stormwater; Weeds/ undesirable vegetation along fenced area; stormwater ditch exit drain on SW corner fence line.



View of SE corner of perimeter fencing around well pad.



Stormwater ditch and low lying area adjacent to North side well pad.

