



Photo 1. View of hill slope where Scotch thistle plants have been cut.



Photo 2. View of Scotch thistle plants in interim reclamation area that appear to have been treated with herbicide. Treated plants are dark leafy material in center of photo.



Photo 3. View of straw blanket placed on cut slope for stormwater control.



Photo 4. View of straw logs place in erosional channel.