



Photo 1. View of newly installed rock check dams on eastern side of access road.



Photo 2. View of northeastern edge of working area downstream from access road that appears to have been recently bladed to divert stormwater flows to the eastern interim reclamation area.



Photo 3. Newly installed rock check dams along the western edge of the access road.



Photo 5. Newly installed berm to divert stormwater flows on the western edge of the well pad.



Photo 5. View of cobble check dam in southwestern corner of working area where diverted stormwater flows exit the project area.



Photo 6. View of Scotch thistle rosette that appears to have been chemically treated.