



Photo 1. View of newly installed straw wattle in northern portion of the project area from northwestern corner facing eastward.



Photo 2. View of newly installed straw wattle in northern portion of the project area from northeastern corner facing westward.





Photo 3. View of repaired gullies, new gravel, and straw wattle in eastern portion of project area.