



Photo 1. View of new cobble placed in gully from top of slope facing downstream.



Photo 2. View of newly graded diversion on eastern edge of project area.





Photo 3. View of new silt trap in northeastern corner of project area.



Photo 4. View of new diversion and berm in northern portion of project area facing northwestward.





Photo 5. View of new cobble placed near entrance of access road.



Photo 6. View of culvert outlet with rock filter dams placed downstream of project area below culvert outlet at access road entrance facing downstream.