



Photo 1. View of new of cobble and earthen berm placed in eastern portion of project area.



Photo 2. View of newly installed cobble and berm along eastern edge of working area.



Photo 3. View of cobble placed in head-cut erosional feature.



Photo 4. View of tree stump from dead tree that was removed.