



Photo 1. View of liner material and trash seen in interim reclamation area.





Photo 2. View of knapweed (likely *Acroptilon repens*) infestation on northern slope within interim reclamation area.





Photo 3. View of western portion of project area from northern edge facing westward. Most of the vegetation is weeds such as knapweed and Russian thistle (*Salsola tragus*).





Photo 4. View of erosional channel in northeastern portion of project area. Channel somewhat obscured by vegetation in photo, but flows from lower left hand corner of photo diagonal toward the upper right hand corner.