

WPX Energy

Unocal GM 11-2

Location # 334771

Subsidence of base



Damaged Straw Bales



Damaged straw bales and debris



Ditch with weed debris. No culvert seen running under road.



Cement ditch with sediment

Looking up fenced section between location entrance and rail road.

Looking east from chain-link fence.



Ditch beginning at intersection



Looking eastward up cement ditch along rail road.



Looking eastward up cement ditch along rail road.



Cement ditch on both sides of road.

Looking east from intersection



Looking west from intersection



Culvert with water line running thru it.



Ditch on north side of road and cleared area along waterline.



North side of access road

Washing of cleared area along waterline.



Ditch collecting sediment



Washing sediment from cleared area along waterline

