

## E 7 OU Pad

Inspection# 675201065

Berm in need of repair.



Methanol tank missing capacity.



Peeling labels on condensate tank.



Rutting on road.

