

WPX Energy

GV 21-35 Pad

Location # 334743

Erosion rills and failed seeding of cut slope



Erosion rills and failed seeding of cut slope



Erosion rills

Erosion rills behind separators



Erosion rills other side of hill behind separators



Sediment build up in the out let of culvert.



Unmaintained bales and failed seeding



Unmaintained waddles washed out of place and into ditch

