

WPX Energy

PA 11-35 Frac Pad

Location # 335391

No berm around tanks.



Tank hatches open on front, back and top of tanks



Produced water tank with hatch open



Perimeter Berm

Traffic damaged berm



Loose compaction of berm



Traffic damaged berm at end of tanks



Erosion and movement of sediment off bank of location.



Loose compaction of ditch



Tank berm into slope wall

Tank berm built into slope wall allowing run on storm water and sediment to collect in berm.

Poor compaction of berm base. Base is soft and spongy from storm water.

