

Site Photos: API# 05-009-06014

Date: January 20, 2015



**photo 1:** Facing south towards the location along the access road.



**photo 2:** Facing south towards the location along the access road. Access road does not have adequate vegetation and has weed growth (kochia).

Site Photos: API# 05-009-06014

Date: January 20, 2015



**photo 3:** East side of location facing west. Location bare of vegetation approx. 120'x120'.



**photo 4:** West side of location facing east. Location bare of vegetation approx. 120'x120'.

Site Photos: API# 05-009-06014

Date: January 21, 2015



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.

Site Photos: API# 05-009-06014

Date: January 21, 2015



**photo 7:** Center of the location facing south.



**photo 8:** Center of the location facing east.

Site Photos: API# 05-009-06014

Date: January 21, 2015



**photo 9:** Facing east, surrounding vegetation around the access road.



**photo 10:** Facing east, surrounding vegetation around the location.