

Location # 324124 Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Inspection Photographs (12 total) 1/20/2015



1. Location (overlaid on Google Earth, 2014).



2. Location entrance (soil pile in background), viewed North.



3. Location Southern perimeter. Interim area is mainly Kochia and Russian Thistle weeds.



4. Rock pile on Location SE corner, viewed North.



5. On Eastern portion of the pad, soil pile is intruding on interim reclamation, without stormwater BMP controls in place.



6. Excessive gravel in interim reclamation areas, (it does not appear that gravel was removed prior to reclamation).



7. NW location interim reclamation area (2 bare spots at 5' x 5' and 12' x 2'). Area is not completely re-contoured.



8. Area around well head is weedy with Kochia.



9. Well head signs meet standards.



10. Well head cellar hole retaining water.



11. Approximately 40' x 70' on Southern side of separators area void of vegetation.



12. Debris by entrance.