



Photo 1. View of well pad from southwestern corner toward center, overlooking area in southern portion of well pad with poor revegetation.



Photo 2. View of area in southern portion of well pad with poor revegetation that needs monitoring. From southern portion facing eastward.





Photo 3. View of vegetation progressing in northern portion of project area from northeastern corner facing westward.



Photo 4. View of rill erosion that needs to be monitored in northwestern edge of project area.