


## **Reference Area Photographs**

**Inspection Conducted on January 30, 2015**


**Encana Truck Rollover Spill into Dry Creek**

**County Road 319 (West Mamm Creek Rd)  
Truck coming from Encana Facility ID #335163**

## Rollover Spill into Dry Creek



Spill occurred on private land, immediately on the border with BLM land. The spill occurred within the internal area of the 317B buffer, flowing into Dry Creek, which is a tributary of the Colorado River. Spill location is identified with a red X.



Truck was transporting produced water from Encana Location Facility ID #335163. Dirt road was muddy. Driver apparently lost control taking a turn. Approximately 80 bbls were spilled.

## Rollover Spill into Dry Creek



Truck was coming down and missed the turn. The truck rolled over and about 80 bbls of produced water were spilled.



Location of the spill. Clayey soil saturated from snow melt. Minimal retention time. Produced water flowed down toward and into the creek. Encana took soil samples at the source and at several location of the streambed (upstream, spill location, downstream).

## Rollover Spill into Dry Creek



Looking East toward Dry Creek.



Looking East. Produced water flowed downhill into Dry Creek.

## Rollover Spill into Dry Creek



Dry Creek flowing North to the Colorado River. Across County Road, Encana Centralized E&P Waste Management Facility # 149004.



Dry Creek flowing North. View from dirt road. Exit side of culvert. Soil sample downgradient of the culver and around the curve as a compliance point.

## Rollover Spill into Dry Creek



Dry Creek. View upstream. See culvert inlet



Dry Creek. View upstream. Ephemeral streambed is about 3 feet wide. Almost fully vegetated. One soil sample was taken upstream of the culvert and one further upstream of the spill location.