

Knight PA 21-4

Inspection# 675201126

Sediment migration by
separator.



Rutting and pooling on
wellhead location.



Erosion across location.



Erosion channel towards
Colorado River.



Erosion channels from
wellhead towards Colorado
River.



Erosion and sediment
migration on south side of
location.



Unused equipment.



Unused equipment.

