

Knight W 6-4 Pad

Inspection# 675201127

Erosion in main road way.

39.46958/-108.0700



Rutting and rilling at entrance to location.



Subsidence on location.

