

## GV 64-5 Pad

Inspection# 675201130

Debris by tank.



Access road with pooling.



Erosion along roadside from  
exit point of roadway  
pooling.

