

# WPX Energy

GM 13-3 Pad

Location # 334788

# Peeling label and rust on tank.



# Unfinished check dam





# Erosion of trap and surrounding ground surfaces



# GM 313-3 No braden head line

