

Site Photos: API# 05-121-10874

Date: January 28, 2015

See Photo 2



photo 1: Access road south towards the location.



photo 2: Pipe Riser was found along the west side of the access road. 39.83686/-102.85991

Site Photos: API# 05-121-10874

Date: January 28, 2015



**photo 3:** Gate and perimeter fence remain around the location.



**photo 4:** There was no wire/fencing along the northeast side of the location

Site Photos: API# 05-121-10874

Date: January 28, 2015




photo 5: Fence appeared to be in good condition on the west side of the location.



photo 6: Guy line anchor was found at the west side of the location at 39.83344/-102.86319

Site Photos: API# 05-121-10874

Date: January 28, 2015



**photo 7:** Area in the center of the location had sparse vegetation approx. 100'x50' in size.



**photo 8:** Facing south at center of the location. Bare are with sparse vegetation 100'x50' in size.

Site Photos: API# 05-121-10874

Date: January 28, 2015



photo 6: North side of the location has sparse inadequate vegetation cover.



photo 6: Facing north, surrounding vegetation outside of the location.