

XTO Energy
Hein 1-2 API 067-09816
Field Inspection Photos 2/4/15

Out of service/ 500 bbl produced
water tank.



Unused equipment on well pad; Tank,
stairs, etc.



Unused equipment on well pad.
Methanol tank, etc.



Breech in location berm; repair needed.



Tank signage needs to be added at battery; to include all components of 210d and list of individual wells being serviced by battery.



Stained gravel under leaking gear box

