

# WPX Energy

Federal GM 32-34 Pad

Location # 335164

# Erosion rills on slope



# Sediment build up in run on ditch





# Erosion rills at outlet of run on ditch





# Erosion under riprap.



# Rills running into check dam.





# Erosion under rip rap of the outlet



# Damage and displaced straw bales

