

WPX Energy

GM 235-34

Location # 324105

Well head



Erosion rill running off location



Erosion rill running off location

Look for location to road



Looking up to location from road



Ditch filled with sediment



Sediment flow headed to access road.



Mud hole in road from storm water flow over road.

