

WPX Energy

GV 23-34 Pad

Location # 335261

No BMPs to prevent storm water flow from seeded slope



Waddles are deteriorated



Loose compaction of check dam



Erosion rills and erosion of ditch



Dam filling with sediment and over flowing water washing outside of ditch

