

Site Photos: API# 05-011-06024

Date: February 5, 2015



photo 1: Facing west along access road to the location. Road is visible and has inadequate vegetation.



photo 2: Pipeline riser remains on the location. Lat/Long: 38.05236/-102.81947

Site Photos: API# 05-011-06024

Date: February 5, 2015



**photo 3:** Center of the location facing north.



**photo 4:** Center of the location facing west.

Site Photos: API# 05-011-06024

Date: February 5, 2015



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

**Site Photos: API# 05-011-06024**

**Date: February 5, 2015**



**photo 7:** East side of the location facing west towards disturbance area.



**photo 8:** West side of the location facing east towards disturbance area.

Site Photos: API# 05-011-06024

Date: February 5, 2015



photo 9: Weed growth (Russian thistle) throughout the location.



photo 10: Facing southeast, surrounding vegetation around the location.