



Photo 1. View of area where pit, old equipment, and debris were formerly located in western portion of the project area. From northern portion facing southward.





Photo 2. View of stormwater erosion channels and unprotected soils in western portion of the project area facing southward.





Photo 3. View of a stormwater erosion channel that directs stormwater discharge outside of the project area (fence in background).