

GV52-3 Pad

Inspection# 675201163

Access road not stabilized
with erosion on road side.



Failed BMP due to road side
erosion.



Location is not stabilized.

