

WPX Energy

GM 226-35 Pad

Location # 324121

Stain down front of tank



Erosion rill running of location at tank battery



Erosion rill running of location at tank battery



Unstable cut slope



Road ditch needs cleaned out and erosion running through ruts

