



Photo 1. View of several musk thistle plants in the western portion of the project area.



Photo 2. View of large (approximately 3 feet tall) Russian thistle plants bordering the western edge of the working area.



Photo 3. View of rill erosion and sediment deposition in and below a portion of the unprotected cut-slope in the eastern portion of the project area.



Photo 4. View of head-cut erosion and sediment deposition in eastern portion of project area.



Photo 5. View of erosional channel in northwestern portion of project area.



Photo 6. View of erosion at culvert outlet on the access road near the entrance to the well pad. Erosion from stormwater flows exiting the culvert appear to have eroded approximately 10 feet of soil.