



Photo 1. View of drainage diversion on the southwestern corner of project area.



Photo 2. View of the top of a newly installed diversion channel in southeastern corner of project area.



Photo 3. View of the bottom of a newly installed diversion channel, hydromulch, and straw wattles. Channel appears to be sufficient to de-energize and filter flows toward the irrigation canal shown in background.



Photo 4. View of area in northeastern corner of project area where diverted stormwater flows from the northern edge of the well pad.



Photo 5. View of newly installed berm and hydromulch in northern and northwestern portions of the project area from northern edge facing westward.