



Photo 1. View of concrete stabilization of northern cut-slope.



Photo 2. View of northeastern edge of project area from mid-eastern side facing northward.



Photo 3. View of armored stormwater diversion from northwestern corner facing eastward.



Photo 4. View of rill erosion forming in southern portion of project area. Successful revegetation of this area would provide better stabilization of these slopes.



Photo 5. View of southeastern portion of project area from mid-eastern edge facing southward. Dried vegetation is predominantly Russian thistle (*Salsola tragus*).



Photo 6. View of southern portion of project area from southeastern corner facing eastward. Vegetation is largely Russian thistle.