

# COGIS - Field Inspection Report

Location ID 312614

Document 2314095

API Number: <b>05-077-08625</b>		Name: <b>BUZZARD CREEK #11-13</b>	
Location: <b>SWSW 11 9S 93W</b>		Lat: <b>39.28637</b> Long: <b>-107.74379</b>	
Operator #:		Operator Name: <b>DELTA PETROLEUM CORPORATION</b>	
Inspection Date: <b>3/19/2009</b>		Inspector: <b>Gary Helgeland</b>	

Inspection was: **Satisfactory**Insp. Type: **CA**Insp. Stat: **PA**Reclamation (Pass, Interim or Fail): **I**P&A (Pass/Fail): **P**

Brhd. Pressure:

Inj. Pressure:

T-C Ann. Pressure:

UIC Violation Type:

Violation: **N**NOAV Sent: **N**

Date Corrective Action Due:

Date Remedied:

## Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
SURFRH	SOME SLIDING OF PAD IN DOWN HILL DIRECTION. WILL REQUIRE MAJOR REHAB.