

## Titanium 26-10-7HI & 2

Inspection# 673401880

Stained soil in perimeter  
berm.



Stained soil at wellhead, no  
wellhead sign



Stained soil from exhaust,  
lube oil barrel without  
secondary containment.



Tubing stored on location.



