



photo 1: Location sign along the access road.



photo 2: Facing north along the access road. Topsoil was not salvaged and is being heavily compacted.



photo 3: Facing north along the access road towards the location.



photo 4: Facing north along the access road towards the location.



photo 5: Southwest corner of the location facing northeast.



photo 6: Southwest corner of the location facing north.



photo 7: Southeast corner of the location facing northwest.



photo 8: Northeast corner of the location facing south.



photo 9: Northeast corner of the location facing east.



photo 10: Topsoil pile at the northeast corner of the location. Approximate size 60'x10'x5'.



photo 11: Facing northwest towards the pit at the north side of the location.



photo 12: North side of the location facing southeast.



photo 13: Northwest corner of the location facing southeast.



photo 14: Lined pit at the northwest corner of location does not appear to have 2ft. of freeboard.



photo 15: Dozer pushing topsoil, leveling the pad. Top soil compacted and being mixed.



photo 16: Facing southeast towards the entrance of the well pad.



photo 17: Facing south along the access road.



photo 18: Vehicle tracking mud onto Hwy 96 from the access road.