



photo 1: North along access road traveling to the location.



photo 2: Facing east along access road towards the location.



photo 3: Southeast corner of pit. Lat/Long: 38.47938/-102.67259



photo 4: Southeast corner of pit. Lat/Long: 38.47936/-102.67194



photo 5: Southwest corner of the location facing northeast.



photo 6: Southwest corner of the location facing north.



photo 7: Southeast corner of the location facing west.



photo 8: Southeast corner of the location facing northwest.



photo 9: Southeast corner of the location facing northwest towards the topsoil pile.



photo 10: Southeast corner of the location facing west towards the topsoil pile.



photo 11: North side of the location facing west. Dark topsoil pile separated from the drilling pit area.



photo 12: North side of the location facing west. Soil pile pushed out from the pit area.



photo 13: It appears topsoil had not been properly segregated.



photo 14: Northwest corner of the location facing south.