



photo 1: Well sign, Anderson 42-18R



photo 2: Well sign, Anderson 42-18V



photo 3: West side of the location facing south. Area has recently been mulched.



photo 4: North side of the location facing southeast.



photo 5: Unused pipe was left at the location.



photo 6: Guy line anchor has fallen over at northeast corner of the location.



photo 7: The location has recently been straw mulched.