



photo 1: Well sign, Anderson 43-18V



photo 2: Well sign, Anderson 43-18R



**photo 3:** Access road towards the location has recently been mulched/seeded.



**photo 4:** Access road towards the location has recently been mulched/seeded.



**photo 5:** Southeast corner of the location facing north.



**photo 6:** Southeast corner of the location facing west.



**photo 7:** The location has recently been straw mulched and likely seeded.



**photo 8:** Fence around the perimeter of the pit. Did not see a marker indicating 2ft. freeboard.